


# TRANS-DATA

ON-BOARD WEIGHT SYSTEMS  
DATA ACQUISITION SYSTEMS

## 4.4.2

### Typical Digital Multi-Meter



1. Function/Range Indicator Switch: Selects the function and range desired.
2. Com Input Terminal (black lead): Ground input connector 500 V (DC + AC peak). Max volts between Com and earth ground.
3. V.O. Input Terminal: Positive input connector for voltage, resistance, and diode test. Maximum input rating is 1000 VDC, 500 VAC (red lead).
4. 200 mA Input Terminal: Positive input connector for a 200mA current (red lead). Fused.
5. Low Battery Indicator.
6. 200 M Setting: To check for **Millivolt Output** of the beam bridge on the terminal block, set indicator to 200 M.
7. 2k Setting: To check **Ohms** resistance across the beam bridge wires, set indicator to 2k.